



David Geffen
School of Medicine

UCLA Health

Software Bugs or Features - Troubleshooting the Black Box: Part 1

Tom Oshiro, Ph.D., DABR
Associate Professor – Radiological Sciences
UCLA David Geffen School of Medicine




Introduction – Projectional X-ray

- Radiology acquisition systems (X-ray, CT, MR, US):
software is a key component

- User interface
- Hardware controllers, drivers

- Unexpected output

- Troubleshooting steps to narrow the root cause
- Work with vendors to understand the inner workings



David Geffen
School of Medicine

UCLA Health

2



Troubleshooting to Solution

- Development of workarounds
 - Dependent on the scenario
 - Actual clinical impact on patient care
 - Vendor limitations



David Geffen
School of Medicine

UCLA Health

3



Case #1: General Radiography Exposure Index

- New Digital Radiographic unit (2016)
- Acceptance testing (regulatory - Pass)
- Exposure Index (EI) validation
 - 5% (within spec)
 - acceptable limit +/- 20% per IEC and vendor

IEC 62494-1
AAPM TG 116
AAPM TG 232

EI = 100 (detector μGy)



David Geffen
School of Medicine

UCLA Health

4

Case #1: General Radiography Exposure Index

- Deviation Index (DI)

- EI_T = Target (aim) EI for the projection
- $EI \ll EI_T$ (noise), $EI \gg EI_T$ (pt. dose)

$$DI = 10 \log (EI/EI_T)$$

- If $EI = EI_T$ then $DI = 0$ (on target)
 - $10 \log (1) = 0$
- $DI \gg 0$ (possibly overexposed)
- $DI \ll 0$ (possibly underexposed)

AAPM TG 232
DI usable ranges
Accounts for equipment and
technologist variability

Case #1: General Radiography Exposure Index

- EI target set at 252 (Abdomen)

Anatomy	Patient Size	Factory Target EI
Abdomen		
antero posterior	Pediatric	252
antero posterior	Adult	252

EI_T



Case #1: General Radiography Exposure Index

- DI validation: AEC
 - AEC Speed: 125
 - EI = 852
- $EI_T = 252$ (default in setup screen)
- Expected DI value = 5.3
 - $DI = 10 \log (852/252)$
- Displayed DI value = 0.2

$$EI = 100 \text{ (detector } \mu\text{Gy)}$$
$$DI = 10 \log (EI/EI_T)$$



Potential Problem

- If the technologist used DI as a feedback mechanism:
 - Patients could be routinely overexposed
 - DI indicating 'in range' but patient would have received 3x dose
- EI target was not displayed on the acquisition display
 - Could not see EI target settings without superuser permissions



Troubleshooting

- Changing factors – **speed**
- Escalation with the vendor (weeks)
 - White paper that described the relationship between AEC speed, the programmed user/default EI_T and the final EI_T
- Bug or feature?
- Workaround
 - Techs instructed not to use DI as a guide, only rely on the EI



Additional thoughts on this case study:


- Speed terms (100,400..) are legacy term (analog) can probably be eliminated from use
 - AEC systems tied to EI targets
 - Straightforward configuration (engineer and technologist)
- Target EI values should be displayed as a guide





Case Study #2 – Mammography Collimation

- New installation: Digital tomosynthesis mammography unit
- Updated model
- Collimation test (light field to x-ray field)
 - 2% SID tolerance (follows radiographic standards)
 - Self developing (Gafchromic) film
 - Failed the test in tomosynthesis mode



David Geffen
School of Medicine

UCLA Health

13



FYI: Possible SAM Erratum

- one 'dimension' – not one 'direction'



David Geffen
School of Medicine

UCLA Health

14




X-ray to light field – Tomo

- Centered Gafchromic strips with light field
- During acquisition, collimators opened
- After acquisition, the collimators close
- No user interaction




Tomosynthesis mode:

- Compliance failed
 - X-ray extends beyond planned area @ left, right, anterior



Prescribed field




Delivered field





Software issue

- Programming of collimation button
- Prior models had deactivated this button (tomo)
- New version was not disabled - allowed beam restriction in tomo
 - When the field size was set smaller - the beam opened up anyway



David Geffen
School of Medicine


UCLA Health

17



Troubleshooting

- Escalated through the vendor
 - Showed difference in operation on systems
 - Acknowledged the 'bug' & issued a patch
- Workaround
 - Advised techs to not to push the collimation button during tomo exposures
 - Same patient dose compared to normal operation (less clinical impact)



David Geffen
School of Medicine

UCLA Health

18



Additional notes

- Tracking down software issues can be time consuming
- No guidebook
 - Professional experience of clinical impact
- Vendor moderated user groups
- Bug reporting systems



Next: Part 2

