



General Radiographic Image Artifacts

The Art of the Image: The Identification and Remediation of
Image Artifacts in Projection Radiography, part II

Alisa Walz-Flannigan, Ph.D. DABR
Mayo Clinic, Rochester, Minnesota
Walzflannigan.alisa@mayo.edu

American Association of Physicists Meeting, Indianapolis
8/7/2013

Types of Radiographic Artifacts

- Acquisition Artifacts
 - Object in beam-CR/DR
 - Backscatter-CR/DR
 - Grid issue-CR/DR
 - Over/underexposure- CR/DR
- Detection artifacts
 - Dirt and dust in reader-CR
 - Imaging plate damage-CR
 - Dead lines/pixels/detector - CR/DR
- Signal Processing Artifacts
 - Bad plate erasure-CR
 - DR lag-DR
 - Saturation-CR/DR
 - Flawed or limited flat-field compensation
 - or shading correction –CR/DR
- Signal Transmission Artifact
 - Readout failure or interference-CR/DR
- Image Processing or image construction issues (stitching)-CR/DR

Could arise from any point in the imaging chain.





Acquisition Artifacts

- Grid issue
- Backscatter

Suppression of anti-scatter-grid lines in an image is handled by a number of mechanisms:

1. Moving grids- Buckys
2. High line rates
3. Grid Removal Software



Wrong line-rate grid



Windowed to show grid-lines



Grid positioned transverse; grid removal software failed

Wireless detector

- Backscatter through the back of the detector.
- Frequently seen with large patients.

Temporary fix: place lead aprons behind the detector

Longer term fix:
More shielding attached to the back of the detector ; provided by vendor.



Detection Artifacts

- Dirt and dust in reader
- Imaging Plate damage


Dirt and dust
in the reader.

Resolved
itself.



Dirt and dust
in the reader.

Reader
cleaned.




Ghosting on dedicated chest CR imaging plate

1mR exposure



Default clinical window-level



20% window


Repeated exposures of similar profile created a ghost. Plates with significant ghosting are replaced.

Phosphor wear


1mR exposure




Default clinical window-level



20% window



Roller damage



Size - 1750 x 2140



Wear marks






Plate yellowing from cleaning agent, Oxivir,

Resolution: Oxivir no longer used for cleaning cassettes for infection control. Switched to SaniCloth.

Phantom image




Image size: 2022 x 2022
View size: 1145 x 831
X: 457 px Y: 282 px Value: -110.00
WL: -227 WW: 644

GE Dig Bad Row Art -

Chest PA and Lateral
Lat Chest Bad column-RAW

Dead line



Im: 1/1
Zoom: 44% Angle: 0
X: 0.00 mm Y: 0.00 mm Z: 0.00 mm



11:02:53 AM
9/6/12
Made In OsiriX

Image size: 2020 x 2020
View size: 1145 x 831
WL: 5348 WW: 3128

GE Dig Bad Row Art :

Chest PA and Lateral
Lat Chest Bad column

Dead line, processed




Im: 1/1
Zoom: 41% Angle: 0

10:56:02 AM
9/6/12
Made in OsiriX

Signal Processing Artifacts

- Bad plate erasure
- DR lag
- Saturation
- Flawed or limited flat-field compensation or shading correction

Latent image in CR from incomplete erasure of previous image.



Visible in regions of high attenuation

Latent image test for that reader





50mR with Cu square



Same plate, 0.1mR no Cu square

Another example of latent image in CR






DR Lag

Lead marker from
prior image is visible


DR Lag
Stitched image




6 seconds later

18 seconds later

Inverse of DR Lag; Lag signal is recorded in signal offset map.





Variation in saturation thresholds visible in raw radiation.
Not a clinical artifact but sometimes asked about by technologists.

Shows the saturation threshold behavior ascribed to the previous image.

7mR, 80kV, 100 mA, 60ms

8.4 mR, 80k V, 100 mA, 71 ms



Structure visible in raw radiation.
Not a clinically relevant artifact






L
2MM




Structure visible in
raw radiation.
Not a clinically
relevant artifact

Siemens DR-
Varian Detector


L
2MM



Visible detector structure
in anatomy



The corduroy artifact seen in the anatomy is caused by a combination of uniformly-spaced components within the detector and the sampling rate in the acquired image




Resolution:

Software update by vendor that changed the sampling rate fixed the problem.



Slot scan system

Lines visible in rapid readout

Resolution:
Slower scan speed.



Defect in calibration. Visible with change in SID.




Resolution: New filter and recalibration.

Visible detector
tiling

Seen with room
temperature
change and use.

Resolution:
recalibration; room
temperature
stabilization





Visible detector tiling

Particular to this view and technique. This artifact is not resolved by detector calibration.


w/l adjustment to better show quadrants


Speckle artifact, after detector drop. Gd₂O₂S Detector



AFTER DROP THAT NEEDED A CAL

Resolved by re-
calibration





Speckle artifact. Gd_2O_2S Detector

(R)

DR 35

Signal Transmission Artifacts

- Failed readout or interference

Reader hesitation

Post-OP L RRP







Plate feed error



R

Attenuation
difference at top
half of image is
from plexiglas used
for positioning

Readout interference.



Readout interference

Source: Bumped
during readout



e

Readout failure



Source:

unknown

Resolution:

Rebooted the system a few times.

Recalibrated the detector.






Image Processing or image construction issues


- Histogram clipping
- Other poor processing
- Image Composition (“stitching”)

Issue: Histogram clipping. Image data outside of the Values of Interest are discarded and not recoverable.



Resolution:


Re-processed the images under a different setting with a fixed latitude
This issue is addressed by an upgrade to vendor software.




Issue: Image processing failure/Overexposure

The detector is not saturated. Image data in the region is recoverable. However, it is difficult to see and must have an extreme window/level to be made visible. It is often seen with small patients in lateral chest images.

Resolution: By selecting “-1” exposure compensation brings the pixel values into a range which fares better with the image processing and remaining image quality is sufficient.




Issue: Incomplete image processing from incorrect shuttering.
Electronic shutter which selects region for processing triggers on the wrong area




Resolution: Shuttering can be manually modified.

VOI LUT not received or recognized




VOI LUT recognized




Issue: VOI-LUT is not transmitted because of incorrect configuration. For the same system, this VOI-LUT is not recognized by downstream viewers.

Stitching artifact



Different projections of the same object are combined into a single image.

Resolution: Vendor employs a different method for stitching where the source is stationary.



General Considerations

- Know how your system works (mechanics/image formation) in order to know what the risk areas are for artifacts and how to troubleshoot
- We rely on technologists to find and report clinical artifacts
 - Promote a culture of safety which encourages reporting
 - Teach techs about what they should be looking for with different systems

Discussion

The Art of the Image: The Identification and Remediation of
Image Artifacts in Projection Radiography, part III


3 mammography cases

3 general cases

CasE A

R
V
RCC

R
V
LCC



Case A


R
V RMLO



R
V LMLO

Case A

Flat Field Test



Case A

CasE B



View: LCC

kVp: 28

mAs: 127

Compression Thickness: 7.2 cm

Compression Force: 20.9 lbs




Case B

kVp: 28

mAs: 75

Compression Thickness: 5.0 cm

Compression Force: 20 lb



Case B


View: Flat Field

kVp: 28

mAs: 65

Compression Thickness: N/A

Compression Force: N/A




Case B

CasE C


Calk Like Artifact RCC

View: RCC
kVp: 26
mAs: 65
Thickness: 39 mm

RCC



Key



Case C

Calc Like Artifact - LMLO



kVp:

mAs:

Compressed Thickness:


Compression Force:

Exposure Index:



Case C

CasE D




Case D

Warning: not enough gray scales (32)
to display the image properly

Courtesy of Ian Honey

CasE E

Case E.1



kV: 108.8

mAs: 2.3

D: 3.570

Clinical EXI 135

W CHEST PA

1


7.55 μGym^2

WW: 3813

WC: 1733

o.p.

Case E.2





CasE F

Image size: 2021 x 2021
View size: 1208 x 1208
WL: 6241 WW: 17630

L
M
P

CHEST_PA_LAT - Chest



Case F

Zoom: 60% Angle: 0
Im: 1/1
Uncompressed
Position: LL

NOT FOR MEDICAL USAGE

1/5/12 7:52:12 AM
Made In OsiriX