



MR Safety: Case Review of Real MRI Safety Incidents

Joel P. Felmlee, Ph.D.

AAPM Summer Meeting 2014

©2014 MFMER | slide 1

Outline

- MR Safety Considerations
 - B0, dB/dt, RF, Acoustic
 - Assessment strategy
- Case reviews
 - Shocked (or not?)!
 - Sacral stimulator (sans wires) - head/ spine
 - Chest expander
 - Tanked (a zone 3 phenomena!)
 - Cochlear implant
 - Stapes Implant



©2014 MFMER | slide 2

MRI Safety Considerations

- B0
- dB/dt
- RF
- Acoustic

- Can we simplify?
- When faced with a patient exam, how do we get started?

ACR Guidance Document on MR Safe Practices: 2013 M. Kanal et. al, J. Magn. Reson. Imaging 2013;37:501-530.



©2014 MFMER | slide 3

MRI Safety: Assessment Strategy

- Know what device is in your patient
 - Manufacturer
 - Model
 - Serial number (if possible)
- Does your patient have an information card?
- Talk to patient, care provider, manufacturer 's rep
- Look in medical notes
- Use internet for:
 - Information from the manufacturer
 - Search device name + " MRI safety"
 - Safety web sites
- Assess risk and benefit with Radiologist



©2014 MPMCH | slide 4

MRI Safety: Assessment Strategy (2)

- Assess your device against MRI safety considerations
 - B0 (attractive force, torque)
 - dB/dt (peripheral nerve stimulation)
 - RF (heating)
 - Acoustic (Loudness)
- Which are relevant to your situation?
- Talk to technologist and Radiologist to assure everyone is understanding and in agreement
- Review plan with Radiologist and Technologist
- Oversee exam, if needed, at the scanner



©2014 MPMCH | slide 5

When imaging devices within a patient in MRI, which of the following is the best first step ?

- 17% 1. change the acquisition to normal mode to reduce dB/dt
- 13% 2. assess whether the device is effected by B0, dB/dt, RF
- 13% 3. conduct a search on the web to determine safety aspects of the device
- 43% 4. know exactly what is in your patient - investigate so that the exact device name, model, and serial number (if available) are known to you
- 13% 5. reduce the RF power (SAR)



©2014 MPMCH | slide 6

Answer

- know exactly what is in your patient - investigate so that the exact device name, model, and serial number (if available) are known to you
- The above allows you to develop a plan

Reference: ACR Guidance Document on MR Safe Practices: 2013 M. Kanal et. al, J. Magn. Reson. Imaging 2013;37:501-530.



©2014 MPMSC | slide 2

MRI Safety Case Review #1

- Physics contacted by MR technologist, patient reports feeling an electric shock during third series of an MRI exam
- Patient removed from 1.5 T MRI scanner
- Patient's vital signs monitored, unstable progression noted, and taken to emergency room
- Patient recovered, and returned for scanning at a later date
- Is this a B0, dB/dt, RF, or acoustic issue?



©2014 MPMSC | slide 3

MRI Safety Case Review #1: What did we do?

- Physics reviewed imaging parameter settings with MR technologist
- Noted Patient issue developed during "T2w GRE"
- "T2 w GRE" used EPI readout*
- MRI Scanner evaluated by service personnel
- Series repeated using same parameters, swapped phase and frequency axes, and Normal mode
- Discussed with Radiologist and with patient (via phone, after the fact)



* Things that make us think, hmmm

©2014 MPMSC | slide 4

MRI Safety Case Review #1 : What did we find?

- MRI Scanner evaluated by service personnel: RF and electric isolation, humidity
 - RF and isolation - No problem found (NPF)
 - Humidity – high, out of spec due to construction in adjacent room
- “T2 w GRE”
 - Very Low SAR*
 - EPI readout*
- Series repeated using same parameters, swapped phase and frequency axes, and Normal mode
 - Same parameters: Freq. encoding along Y*
 - Peripheral nerve stimulation (PNS) occurred*
 - No PNS in other acquisitions*



©2014 MEDICAL | slide-11

MRI Safety Case Review #1 : What did we find?

- Discussed with Radiologist and with patient
- Results so far:
 - Very Low SAR (not RF)
 - EPI readout (gradient dB/dt possible)
 - Significant sensations replicated, but not a “shock”
- Patient was an Electrician and Electrical Engineer
 - Described: sensations start and stop with scan
 - Not electrostatic but patient’s context is important!
- Determination: Peripheral Nerve Stimulation - PNS
- Subsequent scans “successful” using Normal mode with frequency encoding along X (revised protocol)



©2014 MEDICAL | slide-11

When faced with a patient complaint of a “shocking” sensation during gradient intensive scans such as DWI or DTI imaging, which of the following is the most likely cause?

- 10% 1. B0, the static magnetic field induced eddy currents
- 13% 2. gradient dB/dt inducing peripheral nerve stimulation
- 20% 3. RF energy causing heating in tissue and devices
- 30% 4. acoustic energy causing a pressure wave in the magnet bore
- 27% 5. phosphine discharge due to static discharge



©2014 MEDICAL | slide-12

Answer

- gradient dB/dt inducing peripheral nerve stimulation
- The DWI and DTI scans are low SAR and high dB/dt making PNS a likely event.



©2014 MEDTRONIC | 484-11


MRI Safety Case Review #2 A

- Physics contacted by technologist
- Patient called one day prior to brain MRI
- Patient reports having sacral nerve stimulator that has had wires removed
- Patient requests discussion with physicist prior to exam
 - Expressed multiple concerns (Safety, anxiety)*
 - MRI important for care plan*
- Is this a B0, dB/dt, RF, or acoustic issue?



©2014 MEDTRONIC | 484-11

InterStim® Therapy for Urinary Control is indicated for the treatment of urinary retention and the symptoms of overactive bladder



- Neuromodulation sends electrical stimulation to the sacral nerve
- The sacral nerve, in particular, influences pelvic floor behavior and is believed to modulate neural reflexes¹



References: 1. Buback D. AORN J. 2001;73(1):176-190.
<https://professional.medtronic.com/pt/uro/snm/edu/presentations-downloads/index.htm>

©2014 MEDTRONIC | 484-11

Which of the following is a concern in MRI when wires are known to be implanted within your patient?

- 30% 1. B0, the static magnetic field causing attraction of ferromagnetic items
- 20% 2. gradient dB/dt causing PNS
- 13% 3. RF energy causing heating
- 17% 4. loud acoustic noise levels
- 20% 5. program changes in active devices



©2014 MHS&P | 4/4/21

Answer

- RF energy causing heating

Wires present a real risk of heating in MRI, at high current density points where the end of the wire contacts the patient



©2014 MHS&P | 4/4/21

MRI Safety Case Review #3 (Tanked!)

- A green oxygen tank found in zone 3 of MRI area after weekend call at busy hospital




Is this a B0, dB/dt, RF, or acoustic issue?



©2014 MHS&P | 4/4/21

Tank in zone 3 is too close to zone 4!



MRI Safety Case Review #3 : What did we find?

- Ferromagnetic tank was noted in zone 3, but not removed.
- Weekend patient had brought and exchanged tank at MRI as their oxygen tank was low
 - We found that this is common practice
 - Makes ferromagnetic tank control within hospital very difficult
- Elevated issue as process problem
- Communicated to MR technologists via e-mail and “town hall” meeting
- No injuries , identified a process gap and developed a staff education plan to address issue

Which of the following is a concern in MRI when oxygen tanks are found within zone 3?

- 20% 1. B0, the static magnetic field causing attraction of ferromagnetic items
- 17% 2. gradient dB/dt causing PNS
- 17% 3. RF energy causing heating
- 20% 4. loud acoustic noise levels
- 27% 5. program changes in active devices

Answer

- B0, the static magnetic field causing attraction of ferromagnetic items

Deaths have occurred from ferromagnetic oxygen tanks entering zone 4. An area should be designated for storage of these devices outside of zone 3.


Reference: ACR Guidance Document on MR Safe Practices: 2013 M. Kanal et. al, J. Magn. Reson. Imaging 2013;37:501-530.




©2014 MRCR | 48-21

MRI Safety Case Review #4

- A patient with cochlear implant presents at MRI, with care plan to wrap the head to stabilize internal magnet



Internal Device



Sound processor with cable unit

Is this a B0, dB/dt, RF, or acoustic issue?




©2014 MRCR | 48-21


How does a cochlear implant affect MRI?

The internal implant contains a magnet, which holds the external sound processor coil in place. When placed in an MRI scanner, this magnet can cause a blur or 'artifact' over the medical image, which may hinder the Doctor's ability to make an accurate diagnosis of brain scans. As a quarter of all MRI scans are performed on the brain, having the flexibility to remove the internal magnet if required is an important consideration when choosing a cochlear implant.

A 1.5 Tesla MRI scan of a Nucleus® implant recipient with the magnet in place. The yellow line represents implant placement. The implant magnet creates a large blur on the image, hindering an accurate diagnosis.



A 1.5 Tesla MRI scan of a Nucleus implant recipient with magnet removed. The yellow line represents implant placement. The blur on the image is significantly reduced and causes minimal interference with the diagnosis. (Images courtesy of Royal North Shore Radiology (Sydney, Australia)).



Reference: www.Cochlear.com

©2014 MRCR | 48-21

MRI Safety Case Review #4

- A patient with cochlear implant presents at MRI
- Care plan and artifacts discussed with Radiologist
 - A cochlear implant patient's head was wrapped at the scanner prior to MRI - wrap maintains internal magnet position
 - External electronics removed
 - SAR limited to safe levels (1 W/kg) * RF issue
 - dB/dt managed using Normal mode
- Imaging completed successfully



©2014 MGHES | 6/6-23

Which of the following is a concern in MRI when devices contacting electronic circuitry are known to be implanted within your patient?

- 27% 1. B0, the static magnetic field causing attraction of ferromagnetic items
- 13% 2. gradient dB/dt causing PNS
- 20% 3. RF energy causing heating
- 17% 4. loud acoustic noise levels
- 23% 5. program changes in active devices



©2014 MGHES | 6/6-23

Answer

- RF energy causing heating

In this case B0 aspects were managed. Gradient induced programming changes are not known to be a problem for this device at this time.



©2014 MGHES | 6/6-23

MRI Safety Case Review #5 (Stapes)

- A patient presented with a stapes implant
- Specifics (patient verbal – titanium, had previous MRI)
- Literature and safety web sites show a few implants as unsafe
- One radiologists scanned successfully
- Two radiologists did not scan this patient
- Request for information from surgeon, was inconclusive
- What to do?



Is this a B0, dB/dt, RF, or acoustic issue?

©2014 MRF&S | 4/4/14

Ferromagnetic Detection

- Ferromagnetic materials perturb the local magnetic field.
- Field perturbations follow the object as it moves.
- A high sensitivity magnetic gradiometer senses the environmental field gradient.
- Ferroguard is sensitive only to changing magnetic field gradients.
- A moving field perturbation triggers a visual/audible alarm.



No Alarm

Alarm

No Alarm
(no FM
object being
carried)



Slide provided by Metrasens

©2014 MRF&S | 4/4/14

MRI Safety Case Review #5 (Stapes)

- Ferromagnetic detection was positive, suggesting ferromagnetic metal in the head
- Exact device and history remains unknown
- Future scanning considerations are currently the discretion of Radiologist
- This remains an ongoing investigation ...



©2014 MRF&S | 4/4/14

Summary

- Know basic safety principles (B0, dB/dt, RF)
- Communication is key
 - How many of these situations began with call from technologist?
 - Realize patient anxiety may be beyond exam and related to their disease and ultimately affect their communications
 - Critical thinking and discussion with Radiologist is an expected part of our role on the care team



©2014 MRCR | 48-21

References

- ACR Guidance Document on MR Safe Practices: 2013 , JMRI 37:501–530 (2013)
- Vendor websites:
 - www.Medtronic.com
 - <http://www.cochlear.com>
 - <https://www.uwhealth.org>



©2014 MRCR | 48-21
